



## ***IQ Central Vista/Windows 7 Patch***

This patch allows IQ Central to operate on computers that are running either Windows Vista™ or the Windows 7® operating system. IQ Central systems prior to version 1.10 were not able to operate on these versions of the Microsoft Windows operating system. This small software patch will allow these earlier versions of IQ Central to function on the latest releases of Windows. This patch will be installed automatically on all versions of IQ Central after version 1.9.

**Product** ..... **IQ Central Windows Patch**

**Release Date** ..... **August 18, 2009**

### **Product Requirements**

This patch is intended for computers that are running a version of IQ Central prior to version 1.10 and which are using the Windows Vista or Windows 7 operating systems. It should be installed on both IQ Central servers and client workstations that are operating with Vista or Windows 7.

### **Installation**

This patch will be delivered either as a .zip file sent via email from Peek Traffic customer support, or as a self-extracting zip file downloaded from the Peek Traffic website. The file is called **IQCentral\_Vista7Patch.zip** if you received it via email, or **IQCentral\_Vista7Patch.exe** if you downloaded it from the Peek Traffic website. To install the patch, save the file on your PC and double-click it to launch the patch installer. (The .exe version will install the patch installer into the folder **C:\Program Files\Peek Traffic\IQCentral\Vista7Patch**.)

To install the actual patch, double-click on the file: **VBoost6\_VistaFix.reg**. The installation will only take a few seconds. After the patch has been installed, restart IQ Central.




---

**Note** Installing the patch on older versions of Windows will not cause any problems, but the patch will need to be re-installed if you subsequently update your system to Vista or Windows 7 and you are still using a pre-Version 1.9 release of IQ Central.

---

## Additional Guidance on IQ Central

The following additional resources are available for all customers should you have the need for extra guidance concerning the IQ Central software and its use with a variety of hardware.

### Documentation

**Table 1** — Additional documentation available for IQ Central and related hardware

Document	Part Number
IQ Central Release Notes	99-427
IQ Central Help System	<i>Included with product</i>
IQ Central Operating Manual	81-1123
IQ ATC CBD Controller Manual	81-1164
ATC-1000 Operating Manual	81-1285
IQ ATC TS2/2 Controller Manual	81-1190
Peek 3000E Controller Operating Manual	8204C
Peek 3000E Firmware Release Notes	99-332
Peek LMD 9200 Operating Manual	060758
Peek M3000E Master Controller Operating Manual	5928
Peek M3000E Master Firmware Release Notes	99-329
Multisonics 820A OSAM Controller Operating Manual	006922
Multisonics OSAM 32 Master Controller Operating Manual	RM-0891
Traconex TMM500 Master Operating Manual	28027317-001
Traconex 390CJ Controller Operating Manual	MN078056
Transyt 3800EL Master Controller Operating Manual	81-1191
Transyt 1800EL Controller Operating Manual	81-1192

### Technical Support

This contact information will connect you with the IQ software technical support staff of Peek Traffic Corporation, should you require additional help concerning this update.

#### **Peek Traffic Corporation** Software Technical Support

2906 Corporate Way  
Palmetto, FL 34221  
toll free in the U.S.: 1.800.245.7660  
tel: 1.941.845.1200  
fax: 1.941.845.1504  
email: tech.support@peektraffic.com